

	National Aeronautical Laboratory	Documentation Sheet	Document Classification Restricted
Title	: Failure of Tie Rod of Aircraft Towing Tractor	Document No. PD MT 8643	Date of issue: Aug '86
Author(s)	: S.Radhakrishnan, R.V.Krishnan, R.Rangaraju and V.Ramachandran	Contents 7 pages	
Division	: Materials Science	No. of copies: 12	
External participation	:	NAL Project No. MT-9-861, MT-1-167	
Sponsor	: Aeronautics R & D Board	Sponsor's Project No. Aero/RD-134/100/10/	
Approval	: V.Ramachandran	84-85/394	26
Remarks	:		
Keywords	: Aircraft towing tractor, Tie rod, Weld defect		
Abstract	:		

The tie rod of an aircraft towing tractor failed during trial runs. The tie rod had been circumferentially welded on to a bracket. Microscopic examination confirmed that the failure was brittle in nature and due to poor quality weld. With a modification of the weld design, the tie rod has withstood proof loading and there was no cracking after proof loading.